



Year:	1981	Make:	Caterpillar	Hours:	2,366
W.O. #:		Machine Model:	992C	Serial No.:	042X00981
Product Type:	Wheel Loader	Engine Model:	3412	Serial No.:	73W02214

Equipped: Air Conditioning, Bucket - Spade, EROPS, Steering - Wheel, SYKLONE AIR PRE CLEANERS

REPAIRS DIESEL ENGINE

Item	Comments	Parts	Labor	Customer Damage	Approve
Engine Type:	Non-Tier				
A. Oil Level & Filter Condition	OK				
B. External Leakage	OIL COOLER R/S OTHER MINOR LEAKS				
C. Radiator Condition	APPEARS OK CAN NOT SEE COOLANT				
D. Starting Ability	OK				
E. Unusual Noises	OK				
F. Air Cleaner Condition	NEEDS				
G. Gauges	OK				
H. Muffler & Manifolds	OK				
I. Compression In Radiator	NOT SEE COOLANT				
J. Hoses & Belts	OK				

K. Battery Cond./Electrolite	OK				
L. Coolant Protection	LOW				
M. Coolant Conditioner					
N. Engine Oil Pressure	IN GREEN				
O. Miscellaneous	OIL SHOW AT BREATHER				

TRANSMISSION & TORQUE

Item	Comments	Parts	Labor	Customer Damage	Approve
A. Oil Level & Filter Condition	OK				
B. Suction Lines					
C. Oil Pressure					
D. Stall Test					
E. Case & Linkage	OK				
F. Leakage	WET AT PARKING BRAKE AREA AND COOLER				
G. Proper Shifts	OK				
H. Miscellaneous					

REPAIRS STEERING & BRAKES

Item	Comments	Parts	Labor	Customer Damage	Approve
Steering Type:	Wheel: X Stick Cntrl:				
A. Brake Adjustments					
B. Operations	OK				
C. Levels (Overfull)					
D. Brake Fluid Level					
E. Steering Cylinder Condition	LEAKING				
F. Center Pin & Bearing Condition	OK				
G. Pumps & Valves	OK				
H. Drain Air Tanks					

DIFFERENTIALS & PLANETARIES

Item	Comments	Parts	Labor	Customer Damage	Approve
A. Oil Level & Filters					
B. Magnetic Plugs	RS: LS:				
C. Leaks	FORNT SEAL				
D. Case Conditions	OK				
E. Guards					

HYDRAULIC CONTROLS

Item	Comments	Parts	Labor	Customer Damage	Approve
A. Oil Level & Filters	LOW				
B. Cylinders Leaking	LIFT BOTH LEAKING L/S TILT				
C. Lift Cylinder Condition	BOTH LEAKING				
D. Tilt Cylinder Condition	L/S LEAKING				
E. Major Leaks	CYL SERVEAL LINES LEAKING BEHIND TANK				

F. Hoses	SOME WET				
G. Bent/Damaged Linkage	OK				
H. Pump	OK				
I. System Pressure					
J. Cylinder Drift	OK				
K. Lift & Tilt Kickouts	OK				
L. Miscellaneous					

OPERATORS COMPARTMENT

Item	Comments	Parts	Labor	Customer Damage	Approve
A. Seat Controls	OK				
B. Air Conditioner	YES				
C. Heater & Defroster	OK				
D. EMS System	OK				
E. Parking Brake	OK				
F. Wipers & Washers	YES				
G. Mirrors	OK				
H. Horns	OK				
I. Lights	FRONT 12 REAR TWO				
J. Seat Belts	NEEDS				
K. Operators Manual					
L. Backup Alarm	OK				
M. Cab Filters	NEEDS				
N. Cab/Rops (welds, drilled, etc...)	OK				
O. Miscellaneous	-CAB NEEDS SOME WORK IN SIDE				

VEHICLE BODY DAMAGES

Item	Comments	Parts	Labor	Customer Damage	Approve
A. Engine Side Shields	OK				
B. Hood	OK				
C. Fenders	OK				
D. Fuel Tank	OK				
E. Hand Rails	R/R BENT BOLTS BROKE OFF				
F. Radiator Shroud	OK				
G. Grill	OK				
H. Steps	L/S STEP BENT				
I. Belly Pans	OK				
J. Windows	OK				
K. Doors	OK				
L. Decal Condition	FAIR				
M. Miscellaneous					

BUCKET SECTION

Item	Comments	Parts	Labor	Customer Damage	Approve
Type & Size: SP	Part #: C #:				

A. Pin & Bushings	OK				
B. Links	OK				
C. Cutting Edge	50 % Remain				
D. Adapters	OK				
E. Tips	70 % Remain				
F. Corners	OK				
G. Side Cutters					
H. Miscellaneous					
TIRES					

Make		Size & Ply	General Condition	% Remaining	Cost
RF	GOODYEAR	45/65-45 L-5	CAP	145/32	
LF			CUT SIDE TREAD	87/32	
RR				20/32	
LR			CUT OUT SIDE IN TO CORDS	24/32	
Hours					

PRODUCT LINK / VISION LINK

Item	Comments	Parts	Labor	Customer Damage	Approve
A. Product Link Equipped					
B. Registered					
C. "Reporting" into VisionLink					
D. Antenna					
E. Flash files update					

Additional Comments APPEARS TO FUNCTION OK. HAS SEVERAL OIL LEAKS.	Customer Damage: Repair Cost: Appraisal Cost: Specify Clean Paint Cost: Total Cost:
--	--



image_2.jpg



image_3.jpg



image_4.jpg



image_5.jpg